

Reported Lift Incidents Related to Equipment Fault for 2011/2012

Incident Date	Incident Location	Incident Nature	Lift Maintenance Contractor
1/5/2011	Lift No. 1, Tat Cheung House, Po Tat Estate	Trapping of passenger due to defective levelling device	Fujitec (HK) Co., Ltd.
3/5/2011	Lift No. 20, Sun Fong House, Sun Chui Estate	Loss of balance of passenger due to aging of motor-generator set, causing uneven levelling between lift car floor and landing floor.	Kone Elevator (HK) Ltd.
25/5/2011	Lift No. 2, Un Kin House, Un Chau Estate	Trapping of passenger due to defective levelling device	Kone Elevator (HK) Ltd.
20/7/2011	Lift No. 11, Kai Yin House, Kai Yip Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Chevalier (HK) Ltd.
2/8/2011	Lift No. 14, Kai Yin House, Kai Yip Estate	Loss of balance of passenger due to dislodgement of car door safety device causing uneven levelling between lift car floor and landing floor.	Chevalier (HK) Ltd.
30/10/2011	Lift No. 5, Tip Ying House, Butterfly Estate	Loss of balance of passenger due to defective landing door lock device causing uneven levelling between lift car floor and landing floor.	Shan On Engineering Co., Ltd.
11/12/2011	Lift No. 3, Sheung Hing House, Upper Ngau Tau Kok Estate	Trapping of passenger due to dislocation of governor rope causing safety device activated.	Chevalier (HK) Ltd.
16/12/2011	Lift No. 3, Lee Wah House, Lee On Estate	Loss of balance of passenger due to defective speed regulation control board causing uneven levelling between lift car floor and landing floor.	Kone Elevator (HK) Ltd.
16/12/2011	Lift No. 5, Tin Fai House, Shun Tin Estate	Loss of balance of passenger due to defective drive control circuit causing uneven levelling between lift car floor and landing floor.	Shan On Engineering Co., Ltd.

Reported Lift Incidents Related to Equipment Fault for 2011/2012

Incident Date	Incident Location	Incident Nature	Lift Maintenance Contractor
24/12/2011	Lift No. 5, Fu Keung House, Tai Wo Hau Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.