Welding/cutting operations and equipment—important points

- 1. All personnel involved in welding operations should be properly trained and competent.
- 2. Welding/cutting equipment including hose, cables and gauges should be regularly inspected.
- 3. All gas welding/cutting cylinders should be stored properly as per regulations/guidance notes. If oxygen and acetylene cylinders used on site exceed exempted quantities, a valid DG license must be obtained. In any event, they should still be stored in accordance with the *Code of Practice for Safety and Health at Work for Gas Welding and Flame Cutting*.
- 4. Gas gauges should be provided with appropriate flashback arresters.
- 5. For electric arc welding, adequate welding earths and returns should be properly connected to the workpiece.
- 6. Purpose-built trolleys/carriers should be provided for moving gas cylinders.
- 7. Welding operatives should be provided with, and use, adequate protective clothing/equipment. Proper records of issue of such equipment should also be kept.
- 8. Welding operations should be adequately screened or isolated from other workers/passers-by.