

## Welding / Cutting Operations and Equipment - Good Practices



Photo 1

Pressure Gauges and 'Non-return Valves' of Gas Welding Set Maintained in Good Conditions



Photo 2

Anti-electric shock device installed in the arc welding machine



Photo 3

Proper welding return have been provided.