


WORKING AT HEIGHT 高空工作






Guard-rail on Working Platform at Wall Form Panel not Securely Closed 工作台圍欄未有鎖好


Guard-rail at Edge of Retaining Wall was not Properly Installed 未有裝好圍欄



Safety Guard-rail without Toe Board 圍欄欠缺踢腳板




Unsafe Working Platform 不安全的工作平台



Improper Guard-rails Found at the Ladders was not 1 Meter over the Landing Floor Edges as a Hand-rail

欠缺安全圍欄

梯子頂部未有預留高於平台1米以上作為扶手





Missing of Guard-rails at Edges of Scaffolding Platform 棚架工作平台欠缺安全圍欄

Working Platform on Internal Bamboo Scaffolding was not Closely Boarded 未有裝好棚架工作平台

- No safety harness worn by worker/No tagline or Push/ Pullstick used to move metal formwork
- · 工人沒有佩戴安全帶/沒有拉繩移動組件




- · Unsafe working location No fall arresting device
- · 不安全工作地點 沒有防墮裝置




- Rusted fall arrestor / worn lifeline
- 生銹的防墮器/ 損壞的救生繩




- Working platform on external bamboo scaffolding was found not closely boarded
- ·棚架工作台沒有密封




- Opening was not securely protected
- 開口沒有防墮保護



- Unsafe access to working floor
- 不安全進出通道




- Improper working platform
- 不正確的工作台



- No protection was adopted for working at height
- 欠缺保護措施進行高處工作




- Provision of substandard working platform for working at height
- 沒有提供符合標準的工作平台





- Safety harness was not worn properly
- 沒有正確配戴安全帶



- Unsafe access to the workplace
- 不安全進出通道

