
HOUSEKEEPING


工作場所整理

PROJECTING SHARP OBJECT 突出的尖銳物




CONCRETE PIPES WITHOUT SECURE STOPPER

大型石矢渠筒沒有被妥善楔好




Empty gas container found inside planter 用完的氧氣瓶沒有被妥善儲存





HOUSEKEEPING SYSTEM NOT BEING FOLLOWED

沒有依從良好工作場所安排




鐵模沒有足夠支撐 METAL FORMWORK WITHOUT SUFFICIENT SUPPORT





物料隨地亂放 MATERIALS STORED IMPROPERLY




36

突出的尖銳物 PROJECTING SHARP OBJECT




鋼筋放置於主要道路或導致絆倒 METAL BARS PLACED ON THE MAIN ACCESS CAUSING TRIPPING HAZARD




木條不穩固地斜放於通架上 WOOD BATTENS STORED INSECURELY AT MOBILE SCAFFOLD




過山縲絲凸出於進出路徑 PROJECTING BOLTS WERE FOUND ON ACCESS ROUTE




應清除積水以杜絕蚊患 STAGNANT WATER SHOULD BE REMOVED TO ELIMINATE MOSQUITO BREEDING




螺栓沒有作出保護 PROTRUDED BOLTS WERE NOT COVERED




簷篷上有積水 WATER PONDING ON THE CANOPY



物料阻礙通道 MATERIALS OBSTRUCTED THE WALKWAY




物料存放於臨時支架的門架上 MATERIALS WERE STORED ON PLANE FRAMES OF FALSEWORK




突出的鐵釘。

PROJECTING NAILS WERE FOUND.




在通道上堆放雜物

MATERIAL WAS STORED ON THE PASSAGEWAY



沒有為氣瓶提供保護以防倒下;氣瓶沒有存放於指定地方 GAS CYLINDER WITHOUT ANY PROTECTION AGAINST TOPPLING, AND NOT STORED IN DESIGNATED AREA




渠筒沒有楔好。

STACK OF PIPE SECTIONS WAS NOT WEDGED.




通往塔式起重機的通道有絆倒危害(木板)。

TRIPPING HAZARD/OBSTACLE (WOODEN PLANKS) WAS FOUND ON ACCESS LADDER TO TOWER CRANE.



鐵模板沒有足夠支撐。

PANEL FORMWORK WAS NOT SECURELY SUPPORTED.



通道上放置物料。

MATERIAL WAS PLACED ON PASSAGEWAY.



在通道上放置物料。

MATERIALS WERE PLACED ON THE PASSAGEWAY.

