



# SCAFFOLDING





## Scaffolding Support / Safety

Supporting bracket for roof water tank scaffold  
NOT fixed properly



Supporting bracket  
detached from structure





## Scaffolding Support / Safety

Timber boards were nailed to bamboos





## Scaffolding Support / Safety

Improper working platform and NO safety belt and lifeline provided





# LIFT SHAFT OPENINGS





## Protection to Lift Shaft Opening

### Gap left at toe of barrier



[PRE B8.250]



## Site Safety during Lift Door Installation

Toe board and warning sign not provided





# Site Safety during Lift Door Installation

## Toe board and railings not provided







# WORKING ENVIRONMENT





# Stacking Formwork on Temporary Platform

## Platform over public road without end gate





# Precast Facade Unit

## NOT to put other materials at PCF





## Large Panel Formwork

**Hardened concrete laitance NOT cleaned  
before re-use**



**Risk of falling object  
when handling  
formwork at height**

23/08/2008

[CON 2.W1020.4]



## Unsafe Working Platform





## Unsafe Working Platform





## Unsafe Working Platform



07/11/2007



## Unsafe Working Platform







## Unsafe Working Condition





## Site Safety – Works at Height

No proper platform for works at above 2m high





## Unsafe Working Platform



No planking

No railing





## Site Safety

### No protection to edge of excavation





## Site Safety

### Improper fixing of temporary railing on slope





## Site Safety

### Stacking of timber boards at crest of slope





## Site Safety

NO proper barrier / fencing





# Protective Railing to Slab Edge NOT provided at staircase half landing



[PRE.B8.255.4]





## Site Safety no protective railing at slab edge





# Protection to Floor Openings

NO railing and toe board provided





## Protection to Floor Openings

No temporary railing / closed board to slab opening





## Protection to Floor Openings

The trench was not covered up properly by timber boards or other suitable material





## Long Formwork Tie Rods

Excessively long projection / endanger workers





# Nails on Timber Formwork NOT removed after striking





## Gondola Wire / Safety NOT properly protected





## Gondola Wire / Safety

### Protective rubber wrong way installed

Cut end of tubing  
not protecting  
the wire from the  
sharp corner



Cut end of tubing  
facing upwards  
can protect  
the wire from the  
sharp corner





# Safety Lifeline NOT properly protected





# Safety Lifeline NOT properly fixed





## Protection to Dangerous Materials

The gas cylinders to be kept locked and at upright position at all time





## Site Safety Non-compliance

Metal door of debris discharge point at G/F  
unlocked and opened





# STORAGE ON GROUND





## Storage of Large Panel Formwork Rested on timber strips and uneven ground



[CON 2.W010.4]



## Storage of Large Panel Formwork Rested on timber strips and uneven ground





## Storage of Large Panel Formwork

A large panel formwork was found loosely lean on a precast facade causing danger to nearby workers







## Storage of Large Panel Formwork

One not stored to the approved method statement





## Storage of Large Panel Formwork

### Improper storage





## Storage of Precast Facade Units

**Supporting stands NOT rest on level ground**



[CON 5.W560.4]



## Storage of Precast Facade Units Stored NOT against the stand





# Storage of Precast Units

## Precast refuse chutes stored NOT on firm base





# ELECTRIC LIVE CABLES





## Electric Cables Lying on Ground Cases more frequently noted





## Electric Cables Lying on Ground Cases more frequently noted







## Temporary Electric Cables Lying on the floor without protection





## Electric Cables Lying on Ground Immersed in water





## Electric Cables Lying on Ground Damaged

