

## **Executive Summary**

- Working at height, housekeeping, falling objects and electrical installations still remain the key problems in HA sites
- 2. Provision of proper working platforms and safe means of access to workplace are the major areas need to be improved by contractors
- Poor housekeeping remains unsatisfactory and needs special attention.
- 4. Protection against electrical safety should be improved

- 高空工作,工地整理,高空 堕物及電力工作仍然是主要 問題
- 2. 提供工作平台及安全進出口 是主要改善項目

- 3. 工地整理表現未如理想,須 多加注意
- 4. 改善電力安全

2



## GOOD PRACTICE 良好作業方式

- Platform with guard-rails and toe-boards
- 安裝圍欄及踢腳板



## GOOD PRACTICE 良好作業方式

- Steel mesh is provided in lift machine room.













## GOOD PRACTICE 良好作業方式

- Winch with effective guarding
- 絞車安裝有效護罩







Here is the footage of Site Safety Seminar for Capital Works New Works Contracts of Housing Authority which was held on 12 April 2018 The speaker is Senior Consultant of Occupational Safety and Health Council Mr. Jack FONG His presentation topic is Housing Authority Lift and Escalator Nominated Sub-contracts Safety Auditing System (HALENSAS) Version 1.1.1 Findings of the 4th quarter of 2017 and the 1st quarter of 2018

\*\*\*\*\*\*\*\*\*\*\*

(00:36)

These photos refer to the situation of the Housing Authority Lift and Escalator Nominated Sub-contracts Safety Auditing System Generally, protection was provided at the lift well for controlling access For example, there were railing and toe boards and the access paths were in satisfactory condition In addition, there were also some metal plates sealing the gaps in the plant room Safe working procedure was also posted In addition, there were also hand-held tools with hand straps The storage of materials was tidy and the wells were clean and in satisfactory condition Some winches were adequately protected and safe working procedure of the winch was also posted on the site That's it for my sharing today Thank you

Thank you for watching (01:34)