



# Housing Authority Surprise Safety Inspection Programme (SSIP)

Good & Bad Practices for 2023 Q2 & Q3

香港房屋委員會  
突擊安全巡查計劃

2023 Q2 & Q3 良好及不良作業




**職業安全健康局**  
**OCCUPATIONAL SAFETY & HEALTH COUNCIL**

# 得分一覽

## SSIP Median Scores at a Glance

Performance of Contractors





# Summary of Good Practices

## 良好作業摘要

- Good practices were observed including provision of clear identification of No Crane Zone on a timber scaffold on slope, prevention of heat stroke information, use of real time camera monitoring alarm and facial recognition system for safe access to and egress from the demolition site area (to record unauthorized entry) and the storage yard of large metal formwork (to prevent unauthorized entry) respectively, as well as mechanical aids for manual handling and light-duty PPE, etc.
- 良好作業包括：在斜坡杉棚上提供有清晰識別的非機械移動區域、在地盤提供預防中暑資訊、在拆卸工程工地進出口使用實時監控鏡頭警報器記錄未授權進出、在鐵模場的進出口使用人臉識別系統預防未授權進出、提供機械輔助設備進行體力處理操作和輕量型個人防護裝備等。



## GOOD PRACTICE 良好作業方式

在斜坡杉棚上提供有清晰識別的非機械移動區域。

Provision of clear identification of No Crane Zone on a timber scaffold on slope.



Gammon

Pik Wan Road, Site A and Site B

提供輕量型個人防護裝備。

Provision of light-duty PPE.



China State

Hang Tai Road, Ma On Shan Area 86B Phase 2

## GOOD PRACTICE 良好作業方式



在地盤提供預防中暑資訊。

Provision of prevention of heat stroke information.



Techoy

Sheung Shui Areas 4 and 30 Site 2 Phase 1

在拆卸工程工地進出口使用實時監控鏡頭警報器，記錄未授權進出。

Use of real time camera monitoring alarm for safe access to and egress from the demolition site area to record unauthorized entry.



Tysan

Fanling North Area 15 East Phase 2 and Yip On Factory Estate and Shek Lei Interim Housing



## GOOD PRACTICE 良好作業方式



在鐵模場的進出口使用人臉識別系統預防未授權進出。

Use of facial recognition system for safe access to and egress from the storage yard of large metal formwork to prevent unauthorized entry.



Shui On

Sheung Shui Areas 4 and 30 Site 2 Phase 2 and Footbridge Works at Ching Hong Road North Phase 3

提供機械輔助設備進行體力處理操作。

Provision of mechanical aids for manual handling.



Sun Fook Kong

Ma On Shan Road and Hang Tai Road, Ma On Shan Area 86B Phase 1



# Summary of Bad Practices

## 不良作業摘要

- Improvements are needed in fulfilling legal requirements of proper working platforms, closely boarded platforms, fall arresting system, edge protection, safe means of access and egress, safe use of suspended working platform, safe use of working platforms; toe-boards, floor openings, measures of protection against falling objects; material stacking and storage; clear of passageway, site tidiness; lifting operations safety; electrical supply system, etc.
- 需要改進的工作，包括：提供法定要求合適的工作平台、平台密板、防墮措施、樓邊防護、安全進出途徑、安全使用工作平台、吊船；踢腳板、地板孔洞、對高空墮物的保護措施；物件存放；通道暢通、工地整理；吊運安全；供電設備等。



END  
完