


Housing Authority
Surprise Safety Inspection Programme (SSIP)
Good & Bad Practices for 2024 Q4 & 2025 Q1
香港房屋委員會
突擊安全巡查計劃
2024 Q4 & 2025 Q1 良好及不良作業



職業安全健康局
OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance




GOOD PRACTICE 良好作業方式



在工地提供有自動調平功能的動力操作升降台。

Provision of MEWP with Automatic leveling system.



在工地提供有障礙物偵測設備的動力操作升降台。

Provision of MEWP with secondary guarding device (SGD).



GOOD PRACTICE 良好作業方式



提供電力式推動手推車，作為物料運送的輔助設備。

Provision of battery powered wheelbarrow for assisting manual handling operation.





END
完

This is a clip from the 28 April 2025 recording of the
Hong Kong Housing Authority
“Site Safety Seminar for Capital Works New Works Contracts”
The speaker on stage is Mr Steve HU
Senior Consultant of Occupational Safety & Health Council
His topic is
Surprise Safety Inspection Programme Findings
in Quarter 4 of 2024 to Quarter 1 of 2025

(00:27)

Hello everyone, I am Steve HU
I would like to thank the contractor representatives joining online today
for allowing me to share with you
some good practices we observed
during the surprise inspections conducted with the Housing Authority
as well as some areas that still require
everyone’s effort to improve on site

Let us first look at some findings from site inspections
from the fourth quarter of 2024 to the first quarter of 2025

First, let us look at the scores
From the data, there seems to be a trend
showing a slight downward movement,
which deserves everyone’s attention

Let us first look at the scores for the fourth quarter of last year
The highest score among the contractors was 90
The lowest score was 61
The upper quartile was 90
The lower quartile was 80
The median was 85

As for this quarter
although the median remains at 85
the highest score is 93
and the lowest score remains at 61
the upper quartile has dropped to 88
and the lower quartile has also dropped to 79
In other words, there is a slight downward trend
which deserves everyone's attention

Next, I will share with you some photos
Among them, many contractors have performed quite well on site
For example, some Mobile Elevating Work Platforms (MEWPs)
are equipped with automatic levelling functions
This is quite ideal

In addition, Mr Ho also introduced just now about MEWPs
We have also seen that some construction sites
have already adopted equipment with obstacle detection devices
thereby enhancing the safe use of MEWPs

Apart from safety, health is also worthy of attention
Some construction sites use power-assisted trolleys
to replace manual handling
as auxiliary equipment
to reduce the risk of manual lifting
These practices are all worth everyone's reference
Thank you all for listening

Thank you for watching

(02:47)