

## Reported Lift Incident Record Related to Equipment Fault for 2010/2011

Incident Date	Incident Location	Incident Nature	Lift Maintenance Contractor
25/4/2010	Lift No. 4, Wong Shek House, Ping Shek Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Kone Elevator (HK) Ltd.
23/5/2010	Lift No. 6, Fu Yin House, Tai Wo Hau Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.
29/6/2010	Lift No. 8, Shek Fai House, Chun Shek Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Shan On Engineering Co., Ltd.
1/11/2010	Lift No. 2, Wing Tai House, Fuk Loi Estate	Trapping of passenger's hand due to ineffective door sensitive protective device	Kone Elevator (HK) Ltd.
7/12/2010	Lift No. 1, Sau Lok House, Sau Mau Ping Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Fujitec (HK) Co., Ltd.
9/12/2010	Lift No. 3, Oi Ping House, Oi Tung Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.
19/1/2011	Lift No. 4, Hin Yiu House, Hin Yiu Estate	Trapping of passenger due to abnormal elongation of governor rope causing the safety device activated	Sigma Elevator (HK) Ltd.
25/1/2011	Lift No. 3, Lee Shing House, Lee On Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Fujitec (HK) Co., Ltd.
27/1/2011	Lift No. 3, Tat Hin House, Po Tat Estate	Loss of balance of passenger due to dislocation of governor rope causing the safety device activated	Sigma Elevator (HK) Ltd.

## Reported Lift Incident Record Related to Equipment Fault for 2010/2011

<b>Incident Date</b>	<b>Incident Location</b>	<b>Incident Nature</b>	<b>Lift Maintenance Contractor</b>
31/1/2011	Lift No. 2, Ting Cheung House, On Ting Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Shan On Engineering Co., Ltd.
12/2/2011	Lift No. 2, Tak Chak House, Hau Tak Estate	Loss of balance of passenger due to defective control equipment causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.
18/2/2011	Lift No. 2, Tsui Luk House, Tsui Lok Estate	Loss of balance of passenger due to defective levelling device causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.
24/2/2011	Lift No. 1, Tak Chak House, Hau Tak Estate	Loss of balance of passenger due to defective control equipment causing uneven levelling between lift car floor and landing floor.	Otis Elevator Co., (HK) Ltd.
3/3/2011	Lift No. 27, Tai Yee House, Tai Yuen Estate	Trapping of passenger due to defective control equipment causing the safety device activated	Otis Elevator Co., (HK) Ltd.