

Woodworking Machines - Bad Practices



Photo 1

excessive saw dust is
accumulated around bench
circular saw