




MECHANICAL PLANT AND EQUIPMENT

BAD PRACTICE 不良作業方式

- Neutral and earth of the generator were connected together
- 發電機的中線及地線接駁在一起





Good Practice Example:




Reference Photo

BAD PRACTICE不良作業方式

- Improper guarding for electric winch
- 電動絞機的危險部份沒有完全隔開



BAD PRACTICE 不良作業方式



4

Machine Guarding not Provided
沒有提供機器護罩