





WELDING/ CUTTING OPERATION AND EQUIPEMENT


BAD PRACTICE 不良作業方式



2

The casing of electric arc welding machine was damaged
電焊機的外殼損壞

BAD PRACTICE 不良作業方式




3

Damaged earthing connector for arc welding machine
電焊機接地線損壞



BAD PRACTICE 不良作業方式

- A welder was working without proper protection
- 燒焊工人沒有適當保護



BAD PRACTICE 不良作業方式

- Electric arc welding was taken place on wet floor
- 在濕滑的地面上進行電弧焊




BAD PRACTICE 不良作業方式

- Welding process without proper screen
- 焊接時沒有適當使用屏障




BAD PRACTICE 不良作業方式




7

Damaged welding holder
損壞的燒焊鉗



BAD PRACTICE 不良作業方式



8

Substandard welding shield
不合規格的燒焊面盾

