

### PREVENTION OF FALLING OBJECTS

防止高空墜物


### 物料推疊於竹棚架上 MATERIALS STACKED ON BAMBOO SCAFFOLD




# 建築廢料推疊過高並超出窗口高度 THE STACKING LEVEL OF CONSTRUCTION WASTE WAS ABOVE THE LEVEL OF WINDOW OPENINGS



## 鐵模邊出現罅隙(鐵模下是行人通道) GAP EXISTS BESIDE AND BETWEEN METAL FORMWORK (THERE IS A WALKWAY BELOW THE METAL FORMWORK)



應將外牆鐵模平台上的雜物碎料清走 DEBRIS AND LOOSE MATERIALS SHOULD BE CLEARED FROM THE EXTERNAL WALL METAL PLATFORM





#### 樓高七層以上的建築沒有安裝保護簷篷 PROTECTIVE CANOPY WAS NOT INSTALLED FOR A STRUCTURE OF 7 OR MORE FLOORS.



# 出料台上物料堆疊過高 MATERIALS STACKED TOO HIGH ON LOADING PLATFORM

