




Q4 2014 & Q1 2015

## 得分一覽

#### SSIP Median Scores at a Glance



# Summary of Good Practices 良好作業摘要

- Good practices were observed in the provision of suitable anchorage point, suitable bamboo scaffold and working platform; designated access fence; clothes washing and drying unit.
- 良好作業包括:提供有合適 繫穩點;合規格竹棚架及工 作台;明確進出口;提供洗 衣乾衣設備。


#### 流動升降台的危險部份裝有護罩

Guard provided for the dangerous part of Mobile Elevating Working Platform





#### 為斜坡工作提供合適穩固點 Anchorage point with valid testing certificate





#### 為竹棚架提供合適護欄、踢腳板及進出通道

Guard-rails, toe-boards, and safe means of access and egress were provided on the bamboo scaffold.





### 為圍封範圍提供指定出入口

Designated access fence was provided.






#### 為工友提供洗衣乾衣設備

Clothes washing and drying unit was provided for workers.





#### 提供有圍欄的工夫櫈 Provide step platform installed with guard-rails





# 為低於兩米的工作提供有圍欄的工作台 Provide working platform with guard-rails for working below 2m





# Summary of Bad Practices 不良作業摘要

- Improvements are needed in fulfilling legal requirements of proper working platforms on working floor, edge protection, safe means of access and egress, safe use of ladder; toe-boards, floor opening cover, helmet worn with chin strap; gas cylinders stored in designated area, projecting nails and sharp objects removed, passageway kept clear; lifting safety, complete statutory forms; electrical supply system, etc.

# 。 WORKING AT HEIGHT 高空工作





