

Hello everyone.

Let's share with all of you for the topics below for the rest of the time  
good practices of Surprise Safety Inspection Programme of the 2nd and 3rd quarters  
good practices of Surprise Safety Inspection Programme of the 2nd and 3rd quarters  
and the last one is the progress of Occupational Injury and Disease Surveillance  
System of Housing Authority.

Photos and illustrations will be uploaded on the website of Housing Authority.

I would like to make a briefing today.

We appreciate the development of this metal ladder.

By adding a handrail fence next to the access ramp to the material hoist.

It may not be the best method but we can appreciate the improvement made.

Protect the protruding steel bars.

Gondolas workers wear appropriate Y-sharped helmets

Tested lifting gear is ready for contractors to borrow,

it also lists out the maximum gross weight with the certificate for reference.

Implement a good 5S practice for the storage of hand tools.

Pictures are shown to clearly indicate the location of the tools as a reminder.

When the excavator is deactivated,

please use an iron plate to seal up the unused hook

to avoid improper usage.

Special metal frames are needed to hang up the power supply cables at high level.

At the entry and exit,

The sharing of this topic ends here.