

Housing Authority
 Surprise Safety Inspection Programme (SSIP)
 Good & Bad Practices
 香港房屋委員會
 突擊安全巡查計劃
 Q2 & Q3 2020 良好及不良作業




2020 Q3

1

得分一覽

SSIP Median Scores at a Glance



2020 Q3

2

Summary of Good Practices 良好作業摘要


- Good practices were observed in use of RFID technology for alerting site personnel who enter the danger zone of a mobile crane, and in installation of hoist limit switch with adjustable size for mobile cranes.
- 良好作業包括：使用RFID技術提醒操作員有工地人員進入流動式起重機的危險區；及為流動式起重機安裝可調校大小的限高器。

2020 Q3

3

使用RFID技術提醒操作員有工地人員進入流動式起重機的危險區。當工友進入危險區時，機身會發出聲音警報，駕駛室內紅色警示燈亦會亮著。

Use of RFID technology for alerting site personnel who enter the danger zone of a mobile crane. When worker enters danger zone, an audible alarm will be activated and the red warning light in the cabin will also flash.




2020 Q2

4

為流動式起重機安裝可調校大小的限高器

Installation of hoist limit switch with adjustable size for mobile cranes



2020 Q2

5



END
完

2020 Q3

82

现在放映的是 2020 年 12 月 11 日
香港房屋委员会「新工程合约工地安全讲座」的片段
台上讲者是
职业安全健康局高级顾问张名铨先生

他的讲题是
突击安全巡查计划 2020 年第 3 季巡查结果
大家好
想在此分享
在第二、第三季我们的同事就
新工程合约的工地看到的发现
好的当然要学习，不好的就要警惕了
我们已经踏入第八个年头
从 2013 至今年的第二和第三季的分数
在右边可以看到，中位数 92 和 87
有两张幻灯片是分享一些好的
或者我们还未见过比它好的新案例
关于一些吊运的器材
那些重型的吊运机器附近应用 RFID
其实合约是有要求的
但是，不是经常能看到做得足够或做得齐全
我们看到这个合约工程真的做得很好
在这里看到工友的安全帽上贴了 RFID 标签
而在流动式起重机机身有感应器
如果工友进入危险区，机手有红灯指示
同时在机器周边有警号提醒，叫工友注意及避开
机手就要停机指示他离开
如果工友未能及时避开危险范围
这样是好的
另外是吊机
这个就是我们俗称的「冲顶掣」
这些是感应器，我们看到这是可调节的
因为不同的情景下吊运不同物料时
接驳钢缆附近是有些不同的安排
所以这个感应器的大小是可以调教的
我看到也认为是比较有心思的而提出来分享
好，就说到这里
谢谢