




Housing Authority  
Surprise Safety Inspection Programme (SSIP)  
Good & Bad Practices for 2023 Q1 & 2022 Q4  
香港房屋委員會  
突擊安全巡查計劃  
Q1 2023 & Q4 2022 良好及不良作業





**職業安全健康局**  
**OCCUPATIONAL SAFETY & HEALTH COUNCIL**



# 得分一覽

SSIP Median Scores at a Glance





# Summary of Good Practices

## 良好作業摘要

- Good practices were observed including the Provision of protective devices for MEWP in order to alert operators of an overhead obstacle, provision of protection for protruding rebars, provision of power-assisted trolley with “Emergency Stop” and multiple abilities, etc.
- 良好作業包括：在動力操作升降台安裝保護裝置，以便提醒操作員上方障礙物、提供突出鋼筋的保護、提供帶有「緊急停機掣」和其他如傾卸和爬梯功能的電動手推車等。


在動力操作升降台安裝保護裝置，以便提醒操作員上方障礙物。  
Provision of protective devices for MEWP in order to alert operators of an overhead obstacle.






在工地大範圍提供突出鋼筋的保護。

Provision of protection for protruding rebars on large site area.





提供帶有「緊急停機掣」和傾卸功能的電動手推車。  
Provision of power-assisted trolley with “Emergency Stop” and lift  
dump for carrying load.






提供帶有「緊急停機掣」和具備爬梯功能的電動手推車。

Provision of power-assisted trolley with “Emergency Stop” and stair climbing ability for carrying load.





END  
完