


Housing Authority
Surprise Safety Inspection Programme (SSIP)
Good & Bad Practices for 2024 Q1 & 2023 Q4
香港房屋委員會
突擊安全巡查計劃
2024 Q1 & 2023 Q4 良好及不良作業



職業安全健康局
OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance



Summary of Good Practices

良好作業摘要


- Good practices were observed including the provision of fingerprint padlock for tower crane access to prevent unauthorized access, provision of automatic crossing light for workers and provision of mobile noise barriers in rock breaking area, etc.
- 良好作業包括：在天秤出入口提供指紋鎖以防止未經授權人士進入、在車閘出入口提供自動行人指示過路燈、和在打石位置上提供流動隔音屏障等。

GOOD PRACTICE 良好作業方式



在天秤出入口提供指紋鎖以防止未經授權人士進入。

Provision of fingerprint padlock for tower crane access to prevent unauthorized access.



在打石位置上提供流動隔音屏障。

Provision of mobile noise barriers in rock breaking area.



GOOD PRACTICE 良好作業方式



在車閘出入口提供自動行人指示過路燈。

Provision of automatic crossing light for workers.





END
完