




Housing Authority
Surprise Safety Inspection Programme (SSIP)
Good & Bad Practices
香港房屋委員會
突擊安全巡查計劃
Q4 2015 & Q1 2016 良好及不良作業



職業安全健康局
OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance



Note: Max, HQS, Median, LQS, Min are shown for each quarter



Summary of Good Practices

良好作業摘要


- Good practices were observed in ; Provision of suitable anchor point inside the life shaft; Use of hop-up platforms; Provision of certified lifting C clamp for lifting I beams; Trial application of spring grip clip with remote control for lifting sheet piles and H piles Good 5S practice.
- 良好作業包括：於升降機槽內提供合適穩固點；使用合標準功夫凳；提供已檢驗合適的起重裝置作吊運工字鐵；嘗試用專用吊具作吊運H樁；良好5S整理。

於升降機槽內提供合適穩固點。

Provision of suitable anchor point inside the life shaft.




使用合標準功夫凳。
Use of hop-up platform.




於吊運閘板及工字鐵時嘗試使用遙距開關控制之吊具，以減少使用吊人籠。

Trial application of spring grip clip with remote control for lifting sheet piles and H piles to minimize the use of man-carrying cage.



良好5S整理。
Good 5S practice in fitter room.





END
完