



Housing Authority

Surprise Safety Inspection Programme (SSIP)

Good & Bad Practices for 2021 Q2 & Q3

香港房屋委員會

突擊安全巡查計劃

Q2 & Q3 2021 良好及不良作業




職業安全健康局

OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance





Summary of Good Practices

良好作業摘要

- Good practices were observed including the provision of shelter for portable drinking water point; provision of hop-up platform complied with EN131-7, and provision of LED light for each distribution board.
- 良好作業包括：為流動飲用水點提供遮蔭；提供符合歐盟標準EN131-7的功夫檯；及為每個臨時電箱提供LED燈照明。


為流動飲用水點提供遮蔭。

Provision of shelter for portable drinking water point.



提供符合歐盟標準EN131-7的功夫櫈。


Provision of hop-up platform complied with EN131-7.



為每個臨時電箱和工地辦公室提供LED燈照明。

Provision of LED light for each distribution board and site office.





END
完

