



Housing Authority Surprise Safety Inspection Programme (SSIP)

Good & Bad Practices for
2021Q4, 2022 Q1 & Q2

香港房屋委員會
突擊安全巡查計劃


2021Q4, 2022 Q1 & Q2 良好及不良作業



職業安全健康局
OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance





Summary of Good Practices

良好作業摘要

- Good practices were observed including the Provision of covering for floor openings, use of metal scaffold instead of bamboo scaffold during construction of non typical floor, implementation of smart lock arrangement for MEWP and fork-lift trucks, provision of safety nets to prevent falling objects to the excavation, provision of extra identification mark plate for a chain sling, provision of graphical instruction for the controllers of lorry-mounted crane, provision of earthing arrangement for the metal frame of a cordless electric portable tool charging point, provision of cover for the cables on access route to prevent tripping, and provision of blower to enhance ventilation inside floors, etc.
- 良好作業包括：在樓籠孔洞提供覆蓋物、為在建設非標準樓層時使用金屬棚架代替竹棚、為動力操作升降台及剷車提供智能拍卡上鎖制度、提供安全網，防止有物件跌進坑內、為吊鏈提供額外識別標誌(牌仔)、為貨車式起重機控制器提供圖像化指示、為無線手提電工具充電站的金屬架提供接地安排、為橫跨在通道上的電線提供蓋板以防止絆倒及提供吹風機以加強樓層通風等。


在樓籠孔洞提供覆蓋物。

Provision of covering for floor openings.




在建設非標準樓層時使用金屬棚架代替竹棚。

Use of metal scaffold instead of bamboo scaffold during construction of non typical floor.



為動力操作升降台及剷車提供智能拍卡上鎖制度。

Implementation of smart lock arrangement for MEWP and fork-lift trucks.



提供安全網，防止有物件跌進坑內。

Provision of safety nets to prevent falling objects to the excavation.




為吊鏈提供額外識別標誌(牌仔)。

Provision of extra identification mark plate for a chain sling.




為貨車式起重機控制器提供圖像化指示。

Provision of graphical instruction for the controllers of lorry-mounted crane.



為無線手提電工具充電站的金屬架提供接地安排。

Earthing arrangement has been provided for the metal frame of a cordless electric portable tool charging point.



為橫跨在通道上的電線提供蓋板以防止絆倒。


Provision of cover for the cables on access route to prevent tripping.



提供吹風機以加強樓層通風。

Provision of blower to enhance ventilation inside floors.





END
完