



Safety & Health Alert No. 41/2022 Work Safety Alert from Labour Department – Collapse of Reinforcement Bar Structure (8 November 2022)

Date: 21 November 2022 Ref.: HD(C)TS 4/49/26

The Labour Department has newly issued the captioned Work Safety Alert which is available in their website at

http://www.labour.gov.hk/common/osh/pdf/wsa/WSA-Pressed_to_Death_by_Collapsed_Reinforcement_Bar_Structure_EN.pdf

Furthermore, the Labour Department has currently produced twenty-one animation videos on "Dismantling of Truss-out Bamboo Scaffolds", "Electrical Work", "Work at Height Safety", "Safe Operation of Excavator", "Fall through a Floor Opening", "Fall from a Wooden Ladder", "Struck by Excavator", "Struck by Falling Objects during Lifting", "Electrocuted while Clearing Up Electric Arc Welding Equipment", "Trapped by a Lift Car", "Struck to Death due to Bursting of Tyre", "Fall through a Fragile Roof", "Struck by Falling Object", "Fall from a Bamboo Scaffold", "Fall from a Roof Edge", "Electrical Repairing Work", "Crushed by Toppled Metal Panels", "Struck to Death by a Reversing Vehicle", "Flashover occurred at a Fuel Drum while Welding", "Trapped by Dangerous Part of Material Conveyor Belt" (New) and "Fall through a balcony with permanent railings" (New) which have already been uploaded to our website. You may download or browse the animation videos through the hyperlink provided below.

https://www.labour.gov.hk/eng/news/work_safety_alert_video.htm

Should you have any enquiries, please feel free to contact the Labour Department at 2852 4971.

Page 1 SH Alert: 41/2022