

Safety & Health Alert No. 7/2023

Work Safety Alert from Labour Department – Fell Together with a Collapsed Metal Platform (31 January 2023)

Date : 23 February 2023
Ref. : HD2-7/SHU/108-30/14

The Labour Department has newly issued the captioned Work Safety Alert which is available in their website at

[http://www.labour.gov.hk/common/osh/pdf/wsa/WSA-Fell Together with a Collapsed Metal Platform-EN.pdf](http://www.labour.gov.hk/common/osh/pdf/wsa/WSA-Fell_Together_with_a_Collapsed_Metal_Platform-EN.pdf)

Furthermore, the Labour Department has currently produced twenty-one animation videos on "Dismantling of Truss-out Bamboo Scaffolds", "Electrical Work", "Work at Height Safety", "Safe Operation of Excavator", "Fall through a Floor Opening", "Fall from a Wooden Ladder", "Struck by Excavator", "Struck by Falling Objects during Lifting", "Electrocuted while Clearing Up Electric Arc Welding Equipment", "Trapped by a Lift Car", "Struck to Death due to Bursting of Tyre", "Fall through a Fragile Roof", "Struck by Falling Object", "Fall from a Bamboo Scaffold", "Fall from a Roof Edge", "Electrical Repairing Work", "Crushed by Toppled Metal Panels", "Struck to Death by a Reversing Vehicle", "Flashover occurred at a Fuel Drum while Welding", "Trapped by Dangerous Part of Material Conveyor Belt" (**New**) and "Fall through a balcony with permanent railings" (**New**) which have already been uploaded to our website. You may download or browse the animation videos through the hyperlink provided below.

https://www.labour.gov.hk/eng/news/work_safety_alert_video.htm

Should you have any enquiries, please feel free to contact the Labour Department at 2852 4971.