



Safety & Health Alert No. 01/2025 Labour Department Work Safety Alert – Trapped between Elevating Work Platform and Ceiling

Date: 8 January 2025

Ref.: HD2-7/SHU/108-30/14

The Labour Department has issued a Work Safety Alert which is available in their website at

https://www.labour.gov.hk/common/osh/pdf/wsa/WSA-Trapped between Elevating Work Platform and Ceiling-EN.pdf

Furthermore, the Labour Department has currently produced twenty-seven animation videos on "Dismantling of Truss-out Bamboo Scaffolds", "Electrical Work", "Work at Height Safety", "Safe Operation of Excavator", "Fall through a Floor Opening", "Fall from a Wooden Ladder", "Struck by Excavator", "Struck by Falling Objects during Lifting", "Electrocuted while Clearing Up Electric Arc Welding Equipment", "Trapped by a Lift Car", "Struck to Death due to Bursting of Tyre", "Fall through a Fragile Roof", "Struck by Falling Object", "Fall from a Bamboo Scaffold", "Fall from a Roof Edge", "Electrical Repairing Work", "Crushed by Toppled Metal Panels", "Struck to Death by a Reversing Vehicle", "Flashover occurred at a Fuel Drum while Welding", "Trapped by Dangerous Part of Material Conveyor Belt", "Fall through a balcony with permanent railings", "Trapped by Dangerous Parts of Machinery", "Pressed to Death by a Toppled Sliding Gate", "Gas Poisoning in Confined Space for Underground Pipework", "Struck to Death by a Fallen Metal I-beam", "Trapped by Elevating Work Platform (EWP) " and "Fall from Height while Erecting a Truss-out Bamboo Scaffold" (New) which have already been uploaded to our website.

You may download or browse the animation videos through the hyperlink provided below. https://www.labour.gov.hk/eng/news/work safety alert video.htm

If you have any enquiries, please contact the Labour Department on 2852 4971.

Page 1 SH Alert: 01/2025