
Fencing of Working Area with Safety Signs & Notices 進工作出入口有安全圍欄並張貼安 全指引及通告



升降機槽口保持關閉並鎖上









Safety rules and warning notice were displayed at the landing place of lift pit.

安全規則和警告展示在電梯的地方。



# Warning sign was displayed in the lift door

在電梯門展示警告標誌








Passageway was maintained in proper order in the lift machine room

在電梯機房的通道保持順通



Independent life lines were installed to the steel bracket above the car top.

在頂部安裝鋼支架及提供獨立救生繩









Guard-rails and toe-boards were installed on the car top.





安裝護欄和底護板





Metal scaffolding was provided inside the lift shaft together with safety nets. 金屬棚架內軸提供安全網







Eyebolt was installed as the anchor for independent life lines outside the lift door.

電梯外門安裝吊環以作獨立救生繩錨。



Tool box and bucket were provided to the workers. 提供工具箱給工人

Site store room was maintained in clean and tidy order.

儲藏室保持乾淨整潔













Proper Stacking of Materials on Site 正確地放置工具及物料





Electric Cables were Adequately Suspended 電線掛於高位






Safety signs were displayed in the control panel of lift. 安全標誌顯示在控制面板



Emergency stop was installed to the control panel of lift. 安裝緊急停止按鈕在電梯的控制面板。







12 提供急救箱中及有正確的檢查清單





Fire extinguisher was provided and maintained in proper order in the store room

在儲藏室提供有效的滅火器

Safety poster and resuscitation notice were displayed in the store room.

在儲藏室展示安全海報





Trolleys were provided as the mechanical aids for material handling.

提供手推車作為物料搬運機械輔助。

Safety lamp was double insulated type.

雙重絕緣型的安全燈。

Fencing of Working Area with Safety Signs & Notices 進工作出入口有安全圍欄並張貼安 全指引及通告



# Lift Shaft Openings were securely enclosed

升降機槽口保持關閉並鎖上





Notices of Proper Use of Fall Arresting Equipment 正確使用防墮裝置的告示





Provision of proper working platform 提供安全工作平台








Anchorage Points of Lifelines in Lift Shaft

升降機槽內設有防墮裝置包括防墮錨固點







Proper use of the Fall Arresting Equipment 施工時正確使用防墮裝置





Working platform provided with full set of toe-boards and guard-rails in the metal scaffold inside the lift shaft 工作平台有 踢腳板和安全圍欄











Good Housekeeping for Storage of Workers' Personal Equipment 個人防護裝備存儲區








Proper Stacking of Materials on Site 良好工地整理

Provision of fire extinguisher fire extinguisher in lift machine room 在電梯機房提供滅火筒





Dangerous parts of lift motor were effectively guarded 升降機危險部件已有適當保護







Emergency stop switch was fitted on top of lift car 已安裝緊急停止裝置



Establishment of tag out system for testing and commissioning

在測試和驗收升降機時使用標籤識別狀態







Workers Wearing PPE on Site 正確使用個人防護裝備



Provision of Head Lamp 工作時使用頭燈



- Provision of proper working platform.
- 提供安全工作平台.







- Lift shaft opening securely enclosed.
- 電梯槽適當圍封.






- Floor opening clearly labeled.
- ○地洞有清晰標示





- Provision of nylon net in lift shaft to prevent fall of objects.
- 在電梯槽內提供尼龍網以防止物料下墜





- Proper use of safety harness when working
- 正確使用安全帶



- Dangerous parts of lift motor were effectively guarded
- 升降機危險部件已有適當保護






- Proper low voltage hand tools.
- 使用低壓電手工具





- Conduct noise assessment.
- 進行噪音評估.





- Lift car top platform with guardrails & toeboards
- 機頂裝有圍欄及底護板





- Implementation of lock-out system on electrical supply system
- 為供電系統實施上鎖系統





- Safe means of access was provided to lift car top
- 提供安全通道進出升降機頂



