

Protection Against Falling Objects - Bad Practices



Photo 1

Falling objects during lifting operation



Photo 2

Improper storage of spare parts on metal mould



Photo 3

Improper lifting container