

Protection Against Falling Objects - Good Practices



Photo 1

Extra fall protection for bar bending area



Photo 2

Extra fall protection for bar bending area



Photo 3

External Wall Bamboo Scaffold, Safety Nets and Catch Fan Maintained in Good Condition



Photo 4

Large green net erected along the constructed building. It provided an extra protection to the external area workers and the public.