



Safety & Health Circular No. 39 / 2012 Work Safety Alert from Labour Department – Air-conditioning Plant Repair Work on the Roof of a Structure

Date: 29 October 2012 Our Ref. : HD(C)TS 4/49/26

This serves to draw your attention to the Work Safety Alert published by Labour Department (LD) for the captioned subject.

The alert can also be downloaded through the link below: http://www.labour.gov.hk/eng/osh/pdf/Safety_Alert_Repair_of_AC_Plant_Aug12.pdf

If you have any enquiries, please contact the Occupational Safety and Health Branch of the Labour Department on 2559 2297, or email: enquiry@labour.gov.hk.

Page 1 SH Circular: 39/2012