

0 incident  
零事故

# 工程物業管理 安全研討會 2024

Safety Forum for Works and Property Management Services

- 推廣安全文化
- 提高安全意識
- 提升安全及健康標準
- 風險管理



風險管理保平安，善用科技守職安  
Harnessing Risk Management and Technologies  
Safeguarding Occupational Safety and Health

The screenshot displays the 'Vip Wong Road Phase 1 & 2 I/S Monitoring' interface. It includes five CCTV camera feeds (CCTV 1-5) showing various road and construction views. A central 'Real Time Recycling Material' section tracks Plastic (0), Paper (0), Steel (2.33), and Non-ferrous Waste (4.6). Below this, the 'Worker Monitoring' section shows a real-time worker count of 0 out of 67 and an average body temperature gauge. The right sidebar contains an 'Alerts' section with status indicators for missing workers and roads, a 'Deflections' gauge for RM 2.2 (mm), and a 'Details' table listing worker IDs and their status. The bottom of the interface features a large 3D map of the road area.

