HALENSAS - 2013Q4 - 2014Q1 Summary on Good and Bad Practices 安全稽核結果

Occupational Safety and Health Council 職業安全健康局



- Lift shaft opening securely enclosed.
- 電梯槽適當圍封.






- Floor opening clearly labeled.
- 地洞有清晰標示





- Provision of nylon net in lift shaft to prevent fall of objects.
- 在電梯槽內提供尼龍網以防止物料下墜





- Proper use of safety harness when working
- 正確使用安全帶





- Tidy working environment.
- 整潔的工作環境





- Proper low voltage hand tools.
- 使用低壓電手工具





- Display inspection label on portable power tools.
- 在手提電工具上展示檢查標籤.






- Electrical cable hung up.
- 電線高掛.





- Conduct noise assessment.
- 進行噪音評估.





- Provide safety bulletin.
- 提供安全資料板.





- Sufficient stock of PPE.
- 個人防護裝備存量充足.



