




Housing Authority
Surprise Safety Inspection Programme (SSIP)
Good & Bad Practices
香港房屋委員會
突擊安全巡查計劃
Q4 2017 & Q1 2018 良好及不良作業



職業安全健康局
OCCUPATIONAL SAFETY & HEALTH COUNCIL

得分一覽

SSIP Median Scores at a Glance





Summary of Good Practices

良好作業摘要

- Good practices were observed in provide additional label with proper colour code and relevant information for the lifting gear; provide QR Code for downloading lifting safety information
- 良好作業包括：為吊具另外加設標籤以便識別；提供QR碼讓工友下載吊運安全資訊

Provide additional label with proper colour code and relevant information for the lifting gear
為吊具另外加設標籤以便識別



提供QR碼讓工友下載吊運安全資訊

Provide QR Code for downloading lifting safety information





END
完

現在放映的是2018年4月12日

香港房屋委員會

「新工程合約工地安全講座」的片段

台上的講者是

職業安全健康局高級顧問 張名銑先生

他的講題是

突擊安全巡查計劃2017年第4季及2018年第1季巡查結果

(00:31)

現在開始了

我所說的和我同事方先生剛才所說的是同一時段

即2017年的第4季和2018年的第1季

我們的巡查人員去到新工程合約工地進行巡查

直到現在我們已經巡查多年，最新的資料在右手邊

2017年的第4季，我們去了51個工地巡查，成績中位數是91分

剛剛過去的一季，看了47個工地

數目相約，有40多至50個

成績中位數是92分，成績中位數92分及91分是頗理想的

有升有跌，希望大家繼續會做得好，可以減少事故

我們也有發現一些做得好的工地

例如是吊運工具的顏色識別系統，除了塗上顏色之外

亦有機構會加上條碼、標籤，是一種額外的資訊，也是可以的

還有就是剛剛提及的二維碼，通常存放了重要資訊

尤其應用在吊運工具上

大家掃描後就可以看到相關資訊，是一個很好的做法

分享完畢
謝謝

多謝觀看

(02:13)