

HASAS(NW) – 2022Q4-2023Q1
Summary on Audit Findings
安全稽核結果

Occupational Safety and Health Council
職業安全健康局




Content

1. Overview on HASAS (NW) & HALENSAS Performance
2. Summary on Audit Findings 2022 Q4 – 2023 Q1


Overview on HASAS Performance

安全審核表現總覽


Score trends of all HASAS contracts (from 1997 to 2023Q1)



Score trends of all HASAS contracts (from 2011 to 2023Q1)




HASAS



Note : All audits with Part A & Part B score at 70% or above in 2022 Q2 – 2023Q1


— % of projects with Part A & Part B score at 80% or above

HASAS Critical Pass Items




- Element 7 - Job Hazard Analysis
- Section 14.1.4 - Housekeeping
- - Section 14.2.3 - Lifting Operations
- - Section 14.4.1 - Tower Crane
- Section 14.1.3 - Working at height
- Section 14.1.5 - Falling Objects
- Section 14.3.2 - Electrical Supply System
- Section 14.4.2 - Mobile Crane

% of NSCs (EL, FS, AC) with score at 70% or above




	2022 Q2	2022 Q3	2022 Q4	2023 Q1
Electrical audit	24(24)	27(27)	26(27)	25(25)
FS audit	23(23)	26(26)	24(26)	25(25)
AC audit	3(3)	4(4)	4(4)	4(4)



	2022 Q2	2022 Q3	2022 Q4	2023 Q1
Electrical audit	24(24)	25(27)	22(27)	22(25)
FS audit	20(23)	24(26)	23(26)	23(25)
AC audit	3(3)	4(4)	4(4)	4(4)

% of LiftNSC (HALENSAS) with Part A and Part B score at 80% or above



Note : All audits (HALENSAS) with Part A & Part B score at 70% or above in 2022 Q2 – 2023Q1

	2022 Q2	2022 Q3	2022 Q4	2023 Q1
HALENSAS	12(12)	3(5)	3(11)	4(6)

Safe Scaffold and Workplace 安全棚架及工作場所

GOOD PRACTICE 良好作業方式

- Worker anchored lanyard at designated anchorage point
- 工友把尾繩繫穩於指定的繫穩點



GOOD PRACTICE 良好作業方式

- Provision of suitable platform ladder and hop-up platform
- 提供合適梯台及功夫櫈



Good Housekeeping
良好工地管理

GOOD PRACTICE 良好作業方式

- Alerting system was provided for temporary refuse chute
- 提供臨時垃圾槽警報系統



Electrical Works 電業作業方式

GOOD PRACTICE 良好作業方式

- Electric cable was properly protected
- 電線妥善保護



Lifting Operations 吊運工序

GOOD PRACTICE 良好作業方式

- Proper lifting method and trial lifting were implemented
- 使用正確的吊運方法及實施試吊程序



Others
其他

GOOD PRACTICE 良好作業方式

- Provision of protective net for steel bending yard
- 於扎鐵場上方提供保護網



GOOD PRACTICE 良好作業方式

- Provision of gripping hand tool clamp to lift/ move wooden board
- 提供抓握工具夾以搬運木板



GOOD PRACTICE 良好作業方式

- Provision of CCTV system and RFID system for MEWP to alert collision
- 為動力操作升降台提供後視鏡及無線射頻辨識系統以提示碰撞



HASAS(NW) – 2022Q4-2023Q1
Summary on Audit Findings (NSC)
安全稽核結果(指名承判商)

Occupational Safety and Health Council
職業安全健康局



HALENSAS – 2022Q4-2023Q1
Summary on Good and Bad Practices
安全稽核結果

Occupational Safety and Health Council
職業安全健康局



GOOD PRACTICE 良好作業方式

- Lift pit was maintained clean
- 井底保持整潔



The END
Thank You!