

無障礙設施清單	相片
觸覺引路帶和斜道 連接有蓋行人通道，住宅大樓，購物中心，停車場和福利設施	   

無障礙設施清單	相片
升降機 設置在各住宅大樓	 A photograph of an elevator lobby. There are three elevators with stainless steel doors. The walls are made of light-colored wood paneling. A yellow caution sign is placed on the floor in front of the middle elevator. The floor has a patterned tile design with a central area of darker tiles.

無障礙設施清單	相片
可供坐輪椅人士使用的無障礙廁所設施 設置在商場	 The first photograph shows a white pedestal sink with a chrome faucet and a mirror above it. The second photograph shows a white toilet with a raised seat, equipped with metal grab bars on both sides. The third photograph shows a shower area with a white tiled floor, a glass partition, and a metal ramp leading into the shower.
暢通易達停車位 設置在停車場	 The photograph shows a parking space in a multi-level parking garage. The space is marked with yellow diagonal lines on the concrete floor. A white pillar is visible on the left side of the frame.